



SEM TRAINERS & SYSTEMS

WHERE TIME MOVES AHEAD TO KEEP PACE WITH KNOWLEDGE

SEM- Scientific Educative Methods in Science, Engineering & Medicine

Mobile : +91 88495 63724
Mobile 1: +91 98791 03905

Email: sem@semtrainers.com
Website: www.semtrainers.com



Replacement joint for blood pressure arm on KERi™ and GERi™

Item No. LF03351U
Make: Nasco Healthcare, USA

[Read More](#)

SKU:

Categories: Blood Pressure

Product Description

Replacement for the joint for the blood pressure arm on the patient care training manikins KERi™ and GERi™.

Replacement Joint for Blood Pressure Arm on KERi™ and GERi™ (LF03351U) — Genuine OEM Spare Part

The Replacement Joint for Blood Pressure Arm on KERi™ and GERi™ (Item No. LF03351U) is the genuine Nasco Healthcare OEM replacement shoulder joint for the blood pressure training arm fitted on the KERi™ and GERi™ patient care training manikins. It is a direct replacement for the shoulder joint that connects the BP arm to the manikin torso, and is the correct part to order when the joint becomes loose, damaged, or worn through repeated clinical skills training use.

This part is compatible with the following Nasco Healthcare manikin models only:

- KERi™ Patient Care Training Manikin
- GERi™ Patient Care Training Manikin

Using a genuine OEM replacement joint ensures correct fit, proper arm positioning, and consistent BP arm function during auscultation training sessions.

Why Buy from SEM Trainers? SEM Trainers & Systems has over 30 years of experience supplying medical simulators and genuine spare parts to 1,500+ institutions across 28 states in India. We provide pan-India delivery and dedicated after-sales support.

Frequently Asked Questions

Q: Which manikins is this joint compatible with? A: This joint is a direct OEM replacement for the BP arm shoulder joint on the KERi™ and GERi™ patient care training manikins only. It is not confirmed as compatible with other Nasco Healthcare manikin models.

Q: Is this a genuine OEM part? A: Yes. This is a genuine Nasco Healthcare Life/form® replacement part (LF03351U).

Q: What causes this joint to need replacement? A: Repeated attachment and detachment of the blood pressure arm during training sessions causes normal wear on the shoulder joint over time. Replacing it restores correct arm positioning and a secure fit.