SEM TRAINERS & SYSTEMS
WHERE TIME MOVES AHEAD TO KEEP PACE WITH KNOWLEDGE
SEM- Scientific Educative Methods in Science, Engineering & Medicine

Mobile :	+91 88495 63724	**Email:**	sem@semtrainers.com
Mobile 1:	+91 98791 03905	**Website:**	www.semtrainers.com

Right Shoulder Keri/Geri

Item No.	LF04064 NU
Weight	0.212kg
Make:	Nasco Healthcare, USA

Read More

SKU:

Categories: Adult Patient Care

Product Description

Component replacement part for **GERi™/KERi™** Nursing Skills Manikin.

Right Shoulder Assembly for KERi™ / GERi™ Nursing Skills Manikin (LF04064 NU) — Genuine OEM Replacement Part

The Right Shoulder KERi™/GERi™ (Item No. LF04064 NU) is a genuine Nasco Healthcare Life/form® replacement right shoulder assembly for the KERi™ and GERi™ Nursing Skills Manikin range. It is the correct part to order when the right shoulder region of your manikin requires structural replacement — restoring full shoulder range of motion and correct anatomical form without replacing the entire manikin.

Compatible with:

- KERi™ Nursing Skills Manikin (all tiers — Basic, Complete, Advanced)
- GERi™ Nursing Skills Manikin (all tiers — Basic, Complete, Advanced)

The shoulder is one of the highest-wear regions on KERi™ and GERi™ manikins, supporting repeated abduction, adduction, rotation, and hyperextension movements during patient positioning, transfer technique training, and range of motion exercises across many training sessions. Replacing the shoulder assembly with a genuine Nasco Healthcare OEM part restores the correct fit, movement range, and anatomical appearance to the original factory specification.

Why Buy from SEM Trainers? SEM Trainers & Systems has over 30 years of experience supplying medical simulators and genuine spare parts to 1,500+ institutions across 28 states in India. We provide pan-India delivery and dedicated after-sales support.

Frequently Asked Questions

Q: What is the difference between LF04064 NU and LF04063 NU? A: LF04064 NU (0.212 kg) is the complete right shoulder assembly — the full shoulder component. LF04063 NU (0.104 kg) is the right shoulder joint only — the internal joint mechanism. If you are unsure which part your manikin requires, contact SEM Trainers with your manikin's item number and we will confirm the correct part.

Q: Which manikins is this compatible with? A: All tiers of the KERi™ and GERi™ Nursing Skills Manikin range from Nasco Healthcare. Confirm compatibility with your specific manikin model and serial number before ordering.

Q: Is this a genuine OEM part? A: Yes. LF04064 NU is a genuine Nasco Healthcare Life/form® replacement component.

Q: Is a left shoulder assembly also available? A: Contact SEM Trainers to confirm availability of a left shoulder replacement for the KERi™/GERi™ range.