



SEM

SEM TRAINERS & SYSTEMS

WHERE TIME MOVES AHEAD TO KEEP PACE WITH KNOWLEDGE

SEM- Scientific Educative Methods in Science, Engineering & Medicine

Mobile : +91 88495 63724

Mobile 1: +91 98791 03905

Email: sem@semtrainers.com

Website: www.semtrainers.com

Right Shoulder Joint

Item No. LF04063 NU

Weight 0.104kg

Make: Nasco Healthcare, USA

[Read More](#)

SKU:

Categories:Adult Patient Care



Product Description

Component replacement part for W44075/W44021 (1013742/1005597)(KERi™/GERi™ Nursing Skills Manikin)

Right Shoulder Joint for KERi™ / GERi™ Nursing Skills Manikin (LF04063 NU) — Genuine OEM Replacement Part

The Right Shoulder Joint (Item No. LF04063 NU) is a genuine Nasco Healthcare Life/form® replacement shoulder joint component for the KERi™ and GERi™ Complete Nursing Skills Manikin range. It is the correct part to order when the right shoulder joint on your manikin has become worn, loose, or damaged through repeated patient positioning, transfer technique training, and range of motion exercises — restoring full shoulder mobility and structural integrity without replacing the entire

manikin.

Compatible with:

- KERi™ Complete Nursing Skills Manikin — W44075 / Item No. 1013742
- GERi™ Complete Nursing Skills Manikin — W44021 / Item No. 1005597

The shoulder joint on KERi™ and GERi™ manikins is one of the highest-wear components in the range — it supports abduction, adduction, rotation, and hyperextension during positioning and transfer training, and repeated movement across many training sessions causes progressive wear at the joint housing. Replacing the joint with a genuine OEM part ensures the correct range of motion, correct resistance, and correct fit are restored to the manikin's original specification.

Why Buy from SEM Trainers? SEM Trainers & Systems has over 30 years of experience supplying medical simulators and genuine spare parts to 1,500+ institutions across 28 states in India. We provide pan-India delivery and dedicated after-sales support.

Frequently Asked Questions

Q: Which manikins is this shoulder joint compatible with? A: This joint is the OEM replacement for the right shoulder of the KERi™ Complete Nursing Skills Manikin (W44075 / 1013742) and the GERi™ Complete Nursing Skills Manikin (W44021 / 1005597). Confirm compatibility with your specific manikin model and serial number before ordering.

Q: Is a left shoulder joint also available? A: Contact SEM Trainers to confirm availability of a left shoulder joint replacement for the KERi™/GERi™ range.

Q: Is this a genuine OEM part? A: Yes. LF04063 NU is a genuine Nasco Healthcare Life/form® replacement component.

Q: What causes the shoulder joint to need replacement? A: Repeated range of motion exercises — particularly abduction, adduction, rotation, and hyperextension — during patient positioning and transfer training cause progressive wear on the shoulder joint housing over time. This is normal wear for a high-use training manikin.